

PROJECT REPRESENTATIVE'S DAILY REPORT

Pg. 1
 Report No. 017
 Date: 2014-09-10
 Day: Wednesday

Architect: Kang Associates
Project: Renovation and Addition to Tewksbury Town Hall
OPM: CBI Consulting Inc. **Clerk of the Works:** Jeff Barnes
Contractor: G.V.W., Inc.

Weather: 7:30 am: mostly cloudy **Noon:** cloudy **3:00 pm:** mostly cloudy
Temperature: 7:30 am: 58° **Noon:** 69° **3:00 pm:** 70°

Superintendent: Vinnie Bomal

PERSONNEL COUNT	Spec Section	Contractor	Trade	Foreman	Journeyman	Helpers	Total
General Contractor:	Div. 06	GVW	Carpenter	1	0	8	9
	Div. 04		Masonry	0	0	0	0
	09 90 00		Painting	0	0	0	0
Subcontractors:	02 08 00	A & J Demo Services	Asbestos Abatement	0	0	0	0
	26 00 00	Griffin Electric	Electrician	1	0	0	1
	22 00 00	Lapan Mechanical	Plumber	1	0	0	1
				3	0	8	11
Total:							

DAILY REPORT

Activities today:

GVW continues to perform demolition work in the basement. GVW has started demolishing the rooms in the north wing and the ceiling behind the stage.

Carpenters are working to set up roof jacks to access the chimney for demolition. They are also setting up roof jacks to access the cupola.

The electrician is still in the process of removing electrical fixtures and setting up temp power to the building.

The plumber is working in the boiler room making safe and cap the plumbing in order that the GC can remove and demo the plumbing and HVAC equipment.

Copies to: Richard Montuori, Town of Tewksbury
 Ed Johnson, Town of Tewksbury
 Steve Sadwick, Town of Tewksbury
 Wayne Lawson, CBI
 Jenne dos Santos, CBI
 Kaffee Kang, Kang Architects

PHOTO INDEX



Photo showing the wall on the stage removed.



Photo showing workers prepping to install the roof jacks.



Photo showing roof jacks installed on the south elevation.



Photo showing removed fascia on the south elevation. This was removed to expose as-built conditions.



Photo showing demolition of the north wing on the first floor, looking west.



Photo showing the north wing looking east.



Photo showing the ceiling demolition in the basement.



Photo showing pile of MEP debris from today's activities.