

PHOTO INDEX



Photo showing masons pointing the masonry on the southeast elevation of the building.



Photo showing masons working on the south elevation of the south wing.



Photo showing a basement window being in the process of being infilled.



Photo showing carpenters getting LVLs into place to sister against the existing floor joists for the 1st floor.



Photo showing LVLs in place for the 1st floor framing.



Photo showing HVAC workmen assembling ductwork in the attic.



Photo showing some of the ductwork in place at the west end of the attic (above the meeting hall).



Photo showing some of the assembled ductwork.



Photo showing plumbers laying pipe in a trench. This is located at the south side of the basement.



Photo showing some of the piping in place.



Photo showing roofers removing the existing parapet caps on the north elevation.



Photo showing roofers installing hook strips along the parapet on the west elevation.



Photo showing workmen sifting soil and backfilling along a pipe trench.



Photo showing mason infilling an opening in a masonry wall in the basement.