

PHOTO INDEX



Photo showing the concrete pump truck in place pumping concrete into the basement.



Photo showing the workmen spreading the concrete starting east and moving west.



Photo showing the workmen working the concrete into place.



Photo showing the finishing process of the concrete in progress.



Photo showing additional formwork being installed for the addition.



Photo showing abatement crew taping windows before the abatement process begins.



Photo showing a worker abating a window on the north elevation of the north wing.



Photo showing some ductwork installed for the 1st floor.



Photo showing HVAC ductwork in place in the attic.



Photo showing the beginning of the framing for the south stairs (stair #3).



Photo showing a portion of the stud wall for the 2nd floor in place.



Photo showing the sprinkler pipe behind the studs.



Photo showing carpenter installing marine grade plywood at the bathroom locations on the 2nd floor.