

PHOTO INDEX



Photo showing workman installing sprinkler pipe for the meeting hall.



Photo showing some of the sprinkler pipe installed in the meeting hall.



Photo showing additional ductwork installed in the attic.



Photo showing HVAC unit installed in the attic along the east elevation.



Photo showing carpenters installing blocking for the new windows.



Photo showing carpenter working on the infill framing for stair #3.



Photo showing the infill framing for stair #3.



Photo showing the wood stud wall in place for the 2nd floor.



Photo showing mason setting up to infill a window opening on the west elevation of the south wing, basement.



Photo showing mason working on making an existing doorway wider.



Photo showing workmen erecting formwork for the addition.



Photo showing abatement crew working on windows on the south elevation of the south wing.



Photo showing abatement crew prepping windows for removal on the east elevation of the main building.