

PHOTO INDEX



Photo showing soil being moved and stockpiled for backfilling around addition.



Photo showing the backfilling in progress.



Photo showing a workman prepping the wall for form installation.



Photo showing mason working on blocking in the doorways in the basement.



Photo showing mason finishing up the block infill.



Photo showing carpenter working on blocking for window opening.



Photo showing carpenter installing backer rod around a window.



Photo showing stair #3 roughed in.



Photo showing plywood underlayment in place in the meeting hall.



Photo showing meeting hall looking west.



Photo showing meeting hall looking east.