

PHOTO INDEX



Photo showing the meeting hall subfloor being repaired prior to the plywood being installed.



Photo showing a carpenter repairing the subfloor along the south wall of the meeting hall.



Photo showing tin knocker attaching ductwork to HVAC equipment on the 1st floor, south wing.



Photo showing tin knockers installing ductwork and sealing the ductwork joints. This is in the meeting hall.



Photo showing ductwork installed for a piece of HVAC equipment.



Photo showing the basement looking northwest.



Photo showing basement looking southeast.