

PHOTO INDEX



Photo showing carpenter installing wall track for the clerk's office.




Photo showing wall track being installed for the nurse's office.



Photo showing stud framing being prepped for the building inspector's office.



Photo showing one louver in place on the west end of the meeting hall, 2nd floor.



Photo showing carpenters prepping to install the other louver in the west end of the meeting hall.



Photo showing stair #2 completed.



Photo showing some of the plumbing lines in the basement.



Photo showing workman infilling beam pockets for the 2nd floor landing.



Photo showing some of the heating pipes in place in the attic.



Photo showing fan coil unit in the attic of the main building.



Photo showing masonry opening at the clerk's office that is going to be bricked in.



Photo showing mason finishing up at the opening for the lobby of the addition.