

PHOTO INDEX



Photo showing carpenter framing in the opening for the Clerk's office service counter.



Photo showing sheetrock ceiling being installed in the mechanical room in the basement.



Photo showing carpenter framing doorway for storage room in the basement.



Photo showing electrician installing rough wiring in 2nd floor office.



Photo showing window installed in meeting hall on north elevation.



Photo showing framing stock and plumbing supplies stored in the basement.



Photo showing plumbers installing piping in the basement.



Photo showing tin knocker installing ductwork in the basement.



Photo showing framing and mechanical equipment in place.