

PHOTO INDEX



Photo showing carpenters starting to install the plywood subfloor.



Photo showing carpenter shimming joists before the new subfloor is installed.



Photo showing the plywood subfloor being installed.



Photo showing the wall blocking installed in the bathrooms. The blocking is used to secure appurtenances such as grab bars, toilet paper dispensers and sinks.



Photo showing typical wall blocking configurations.



Photo showing some of the fire suppression equipment installed.



Photo showing electric panel in place in the 2nd floor hallway.



Photo showing plumber getting ready for rough inspection.



Photo showing HVAC mechanic working in the mechanical room that will service the vault.



Photo showing some of the duct insulation in place.



Photo showing workman installing duct insulation.



Photo showing some piping insulation in place.

Copies to: **Richard Montuori, Town of Tewksbury**
Ed Johnson, Town of Tewksbury
Steve Sadwick, Town of Tewksbury
Wayne Lawson, CBI

Jenne dos Santos, CBI
Kaffee Kang, Kang Architects
Jennifer Pincus, Kang Architects
Bob Harukewicz, GVW Inc.