

PHOTO INDEX



Photo showing workmen clearing debris from snow removal operations.



Photo showing mason working on the masonry wall in the lobby.



Photo showing delivery truck with the vault.



Photo showing the vault starting to be offloaded.



Photo showing vault components being offloaded.



Photo showing vault panels being brought to the building.



Photo showing vault panels being readied to remove.



Photo showing vault components stored in the basement.



Photo showing carpenters installing GWB on the 2nd floor.



Photo showing insulator plying his trade on the VRV piping in the basement.



Photo showing carpenters putting temp handrails back in place after installing GWB in the stairwell.



Photo showing stairwell #3 with GWB installed.

Copies to: **Richard Montuori, Town of Tewksbury**
Ed Johnson, Town of Tewksbury
Steve Sadwick, Town of Tewksbury
Wayne Lawson, CBI

Jenne dos Santos, CBI
Kaffee Kang, Kang Architects
Jennifer Pincus, Kang Architects
Bob Harukewicz, GVW Inc.