

PHOTO INDEX



Photo showing fire protection crew working inside a soffit to adjust the sprinkler system.



Photo showing workman insulating HVAC piping.



Photo showing carpenter installing sheetrock in an office in the basement.



Photo showing acoustical insulation being installed.



Photo showing workman welding vault panels.



Photo showing workman applying strips of the insulation over the seams in the panels as an added safety measure against heat ingress.



Photo showing the start of the staging installation.



Photo showing stairwell #2 being taped and mudded.



Photo showing fire alarm wiring being installed on the 1st floor.



Photo showing mason bricking in the doorway at the basement level.

Copies to: **Richard Montuori, Town of Tewksbury**
Ed Johnson, Town of Tewksbury
Steve Sadwick, Town of Tewksbury
Wayne Lawson, CBI

Jenne dos Santos, CBI
Kaffee Kang, Kang Architects
Jennifer Pincus, Kang Architects
Bob Harukewicz, GVW Inc.