



# PHOTO INDEX



Photo showing HVAC mechanic laying out to install equipment in the north wing of the main building.



Photo showing equipment in place.



Photo showing ductwork in place on the 2<sup>nd</sup> floor.



Photo showing carpenter installing wood blocking in window opening.



Photo showing carpenter installing wood blocking in a basement window opening.



Photo showing carpenter installing joist hangers at post locations where the joists were cut to accommodate the posts.



Photo showing joist hangers installed.



Photo showing blocking that was installed around the post bases.



Photo showing the framing for stair #3 taking shape.



Photo showing carpenter laying out wall locations for the 2<sup>nd</sup> floor.



Photo showing mason parging in voids and holes in masonry.



Photo showing mason installing waterproofing to window blocking.



Photo showing concrete being pumped into the forms for the elevator shaft foundation.