



# PHOTO INDEX



Photo showing the crew starting the excavation for the installation of the drain manhole on Town Hall Ave.



Photo showing the start of the excavation.



Photo showing the existing drain pipe that will be tied into the new drain manhole.



Photo showing the manhole in place and a workman grouting around the drain pipes with a non-shrink grout.



Photo showing the manhole in place and covered.



Photo showing workman installing the formwork and reinforcement for stairs that will lead to the ground level once the construction is complete.



Photo showing the formwork completed.



Photo showing vent and waste stacks in place.



Photo showing plumbers setting up to core holes from drain lines.



Photo showing workman sealing around a louver on the west elevation.



Photo HVAC technician testing the system with pressured air.



Photo showing electrician working the in the basement.

Copies to: **Richard Montuori, Town of Tewksbury**  
**Ed Johnson, Town of Tewksbury**  
**Steve Sadwick, Town of Tewksbury**  
**Wayne Lawson, CBI**

**Jenne dos Santos, CBI**  
**Kaffee Kang, Kang Architects**  
**Jennifer Pincus, Kang Architects**  
**Bob Harukewicz, GVW Inc.**