



# PHOTO INDEX



Photo showing carpenter working on the ceiling framing for the stairwell in the addition.



Photo showing ceiling framing in place in the stairwell.



Photo showing carpenters working on the layout of the lobby entrance.



Photo the door frame to the elevator lobby being installed.



Photo showing ceiling furring installed on the canopy for the lobby entrance.



Photo showing bollards in place and grounding wire buried. This is ready for the transformer.



Photo showing RTUs on the addition roof hooked up to the power supply.



Photo showing sprinkler riser being installed in the mechanical room.



Photo showing sprinkler technician installing sprinkler piping in the addition.



Photo showing ceiling grid being installed in a basement office.



Photo showing rails for the vault shelving system in place, ready to be installed.

Copies to: **Richard Montuori, Town of Tewksbury**  
**Ed Johnson, Town of Tewksbury**  
**Steve Sadwick, Town of Tewksbury**  
**Wayne Lawson, CBI**

**Jenne dos Santos, CBI**  
**Kaffee Kang, Kang Architects**  
**Jennifer Pincus, Kang Architects**  
**Bob Harukewicz, GVW Inc.**