

PHOTO INDEX



Photo showing mason starting to address the masonry on the south elevation.



Photo showing site crew continuing the installation of the granite curbing.



Photo showing electrician working on finish wiring.



Photo showing drinking fountain installed on the 2nd floor.



Photo showing carpenter installing dentals beneath the gutter along the north elevation of the meeting hall.



Photo showing elevator mechanic continuing with elevator installation.



Photo typical mop sink set-up in place.



Photo of the 2nd floor corridor looking north. The doors and hardware are in, lights are on.

Copies to: **Richard Montuori, Town of Tewksbury**
Ed Johnson, Town of Tewksbury
Steve Sadwick, Town of Tewksbury
Wayne Lawson, CBI

Jenne dos Santos, CBI
Kaffee Kang, Kang Architects
Jennifer Pincus, Kang Architects
Bob Harukewicz, GVW Inc.