

# Photo Album for Tewksbury, MA Job 30270 September 2, 2016

Your new Pierce apparatus is now in production. This week the cab was fabricated and began the paint process in metal finishing. The pump plumbing began fabrication. Next week the cab should be nearing completion in paint. The body is scheduled to begin fabrication.



DSC00058



DSC00059




DSC00060



DSC00061



DSC00062



DSC07157



DSC07158



DSC07159



DSC07160